Page: 1

Date: 08/11/23 at 10:14 AM

Aqua Solutions, Inc. 6913 Highway 225 Deer Park, TX, 77536 281/479-2569

Certificate of Analysis / QC Results

Customer PO #:

| Packaged Pro | duct: H3012 | | | |
|------------------------|---------------|-------------------------|---------------|--------|
| - | | EN PEROXIDE 35% FOR DIL | UTIONS | |
| Test | | Target/UOM | Range | Result |
| ASSAY OF MATERIAL | | 35.0% TO 36.0% | - | 35.44% |
| | | % | | |
| Samp | | | | |
| Teste | | | | |
| Teste | | | | |
| Reco | rded 08/11/23 | | | |
| COLOR | | 22 MAX | | 3 АРНА |
| | | PT-CO | | |
| Samp | ole ID | | | |
| Teste | ed 08/11/23 | | | |
| Teste | er TBUR | | | |
| Reco | rded 08/11/23 | | | |
| PH OF PRODUCT/SOLUTION | | 1.700 | 0.000 - 3.700 | 3.000 |
| | | PH | | |
| Samp | ole ID | | | |
| Teste | | | | |
| Teste | | | | |
| Reco | | | | |
| PPM TIN | | 295 | 260 - 325 | 289 |
| | | PPM | | |
| Samp | ole ID | | | |
| Teste | | | | |
| Teste | | | | |
| Reco | rded 08/11/23 | | | |
| STABILITY, % (24 HOUR) | | 97.0% MIN | | 99.2% |
| Samp | | | | |
| Teste | | | | |
| Teste | | | | |
| Reco | | | | |
| STABILITY % (6% | | 90.0% MIN | | 90.0% |
| Samp | | | | |
| Teste | | | | |
| Teste | | | | |
| Reco | | | | |
| Lot # 3 | | | | |
| | | | | |
| Made 0 | 8/08/23 | | | |

Quality Manager