

Page: 1

Date: 04/03/24 at 4:19 PM

Aqua Solutions, Inc. 6913 Highway 225 Deer Park, TX, 77536 281/479-2569 Certificate of Analysis / QC Results

Customer PO # :

Packaged Product:	P1033			
	PENTANI	E (n-PENTANE 99%)REAGENT GRAI	DE	
Test		Target/UOM	Range	Result
ASSAY OF MATERIAL		MIN 99.0%	<u> </u>	99.7%
		%		
Sample ID				
Tested	04/03/24			
Tester	TBUR			
Recorded	04/03/24			
SULFUR (%)		MAX 2 PPM		<0.1 PPM
		%		
Sample ID				
Tested	04/03/24			
Tester	TBUR			
Recorded	04/03/24			
NONVOLATILE MATTE	R (GM/100	MAX 1.0 MG/100ML		0.1
ML)		GM/100ML		
Sample ID				
Tested	04/03/24			
Tester	TBUR			
Recorded	04/03/24			
SAYBOLT COLOR		MIN +30		+30
		COLOR		
Sample ID				
Tested	04/03/24			
Tester	TBUR			
Recorded	04/03/24			
CORROSION, COPPER	STRIP	MAX 1		1-A
		CORROSION		
Sample ID				
Tested	04/03/24			
Tester	TBUR			
Recorded	04/03/24			2.224
ISOPENTANE		MAX 0.75%		0.3%
<u> </u>		%		
Sample ID	0.4/00:5			
Tested	04/03/24			
Tester	TBUR			
Recorded	04/03/24			
Lot # 409223				
Made 04/01	./24			



Page: 2

Date: 04/03/24 at 4:19 PM

Aqua Solutions, Inc. 6913 Highway 225 Deer Park, TX, 77536 281/479-2569 Certificate of Analysis / QC Results Customer PO #:

Quality Manager